

TRACK INSPECTION REPORTING FORM

Name

Michael Billard

Date

1-22-2013

Page 1 of 1

(Please Print)

Watchman

G. Ham

W.O Number

1157930

Inspected From

Hunt Valley

To

Lutherville

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

No new defects noted

Track inspection complete

Were Switch In the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes NO

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Michael Billard

Supervisory Certification

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: [] Select Action []

Quick Reporting Specifications

Work Order: 1157930 TEAM ONE - SECT 1: HV/LU - CM 902N TO

Classification: MTA \LTRAIL MTA - LTRAIL

Asset: []

Alias: []

Location: CHAIN_MARKI LT Rail Chain Markers

Work Location: []

Work Group: MTA527

Site: LTRAIL

Status: COMP

Priority: 1

Work Type: PM

Crew: DAY-A

Warranty Situation Present? N

Maintenance Alert?

Work Details

Component: []

Position: []

Reason for Repair: []

Work Accomplished: []

Part Failure: []

Parent WO: []

Telematics Code: []

Telematics Transaction: []

GL Account: J05-####-052

Total Planned Cost: 0.00

Total Actual Cost: 525.80

Repair Limit Amount: []

Reported By: MTACRON

Reported Date: 07/22/13 12:22:46 AM

Asset Details

Primary Meter

Multiple Assets, Locations and CIs: [] Filter []

Tasks: [] Filter [] 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	[]	[]	N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI	[]	[]	N			NONE	COMP

Labor Materials Tools Failure Reporting

Labor: [] Filter [] 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
[]	MPOLLARD	✓	07/22/13	07:00:00	03:00:00	8:00	26.29	N	N/A
[]	GLAM	✓	07/22/13	06:00:00	02:00:00	0:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name G. LAM

Date 7-23-13

Page / of /

(Please Print)

Watchman Schisler

W.O Number 1157250

Inspected From

To CS

[illegible]

Item	COMMENTS
------	----------

NO NEW DEFECTS NOTED IN AREA

Were Switch In the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ☒

SPECIAL INSPECTION Yes _____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find:

Select Action

Quick Reporting

Specifications

Work Order 1157250 TEAM TWO - SECT 2: LU/CS - CM 586N TO
Classification MTA \LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARK LT Rail Chain Markers
Work Location
Work Group* MTA527

Site LTRAIL

Status COMP

Priority 1

Work Type* PM

Crew

Warranty Situation Present? N

Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-####-052

Total Planned Cost 0.00

Total Actual Cost 630.98

Repair Limit Amount

Reported By MTACRON

Reported Date 07/21/13 12:35:27 AM

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Tasks Filter 1 - 2 of 2

Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 3 of 3

Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	✓	07/23/13	05:30:00	01:30:00 F	8:00	26.29	N	N/A
	WBRYANT	✓	07/23/13	05:30:00 F	01:30:00 F	8:00	26.29	N	N/A
	GLAM	✓	07/23/13	05:30:00 F	01:30:00 F	8:00	26.29	N	N/A

Select Labor

Select Planned Labor

New Row

TRACK INSPECTION REPORTING FORM

Name

Billard

Date _____

7-23-2013

Page

of

(Please Print)

Watchman

Please Print)
Rabette

Inspected From

Cold Spring

To

Camden yards Pennine W.O Number _____

W.O Number

1157330

[illegible]

Item	COMMENTS
------	----------

No new defects noted

Track inspection complete

Were Switch in the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Track Inspector Signature Michael L. Collard

Supervisory Certification

ion M. Bayle

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1157330	TEAM ONE - SECT 3: CS/CY/PENN - CM 23	Site	LTRAIL
Classification	MTA \LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARKI	LT Rail Chain Markers	Crew	DAY-A
Work Location			Warranty Situation Present?	N
Work Group	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	434.47
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/21/13 12:39:34 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs

Tasks

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDAR			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	✓	07/23/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	ARABETTE	✓	07/23/13	07:00:00	12:30:00	0:00	27.17	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name G. LAM

Date 7-24-2013

Page 1 of 1

Watchman BRYANT

Inspected From CAMDEN

To LINTHICUM

W.O Number 1149311

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	CM 030+20		1149311	1	W	N/A	J301	301.332	Y	N
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

7 TIES Pumping UNDER I.J. I.J ALSO NEEDS OVERFLOW
METAL GRINDER OUT FROM BEING BATTERED

Were Switch in the area of Inspected

Yes ☒

NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☒

SPECIAL INSPECTION

Yes ☐

NO ☒

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

TRACK INSPECTION REPORTING FORM

ame

Rollard

(Please Print)

Date _____

7-24-2013

Page

1 of 2

Watchman

Please Print) Kabette

Inspected From

Linthicum

To

From we 11

W.O Number

1156582

BWT.

[illegible]

Item

COMMENTS

Broken lid on cover on Fiber optic cables

Track inspection complete

Were Switch In the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Track Inspector Signature
Michael L. Ballard

Supervisory Certification

TRACK INSPECTION REPORTING FORM

ame

Rollard Rabette

Date _____

7-24-2013

Page 2 of 2

2

(Please Print)

Watchman

W.O Number

1156582

Inspected From

Cromwell याद To

To

[illegible]

Item	COMMENTS
------	----------

No new defects noted

Yard inspection complete

Were Switch In the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☐ NO ☐

NO

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1156582 TEAM ONE - SECT 5 - CM 355S/488S AND
Classification: MTA \LTRAIL MTA - LTRAIL
Asset:
Alias:
Location: CHAIN_MARK LT Rail Chain Markers
Work Location:
Work Group: MTA527

Site: LTRAIL
Status: COMP
Priority: 1
Work Type: PM
Crew: DAY-A
Warranty Situation Present?: N
Maintenance Alert?:

Work Details

Component:
Position:
Reason for Repair:
Work Accomplished:
Part Failure:
Parent WO:
Telematics Code:
Telematics Transaction:
GL Account: J05-####-052

Total Planned Cost: 0.00
Total Actual Cost: 434.47
Repair Limit Amount:
Reported By: MTACRON
Reported Date: 07/20/13 12:43:15 AM

Asset Details

Primary Meter

Multiple Assets, Locations and Cls Filter

Tasks Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	✓	07/24/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	ARABETTE	✓	07/24/13	07:00:00	12:30:00	0:00	27.17	N	N/A

Select Labor

Select Planned Labor

New Row

TRACK INSPECTION REPORTING FORM

Name G. LAM

Date 7-24-2013

Page 1 of 1

(Please Print)

Watchman BRYANT

Inspected From CAMDEN

To Linthicum

W.O Number 1149311

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	EW	No.	Comp.	Defect	S/Y/R	Y/N
1.	CM 030+20		1149311	1	W	N/A	J301	301332	Y	N
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

7 TIES Pumping UNDER IJ. IJ Also needs overflow metal Grinded out from being battered

Were Switch in the area of Inspected

Yes ☒

NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☒

SPECIAL INSPECTION

Yes ☐

NO ☒

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

[Signature]

Quick Reporting (Tr) Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action [Icons]

Quick Reporting Specifications

Work Order	1149311	TEAM TWO - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type*	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group*	MTA527		Maintenance Alert?	<input type="checkbox"/>

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/13/13 12:30:05 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Download [Icons]

Tasks Download [Icons]

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDAR			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Download [Icons]

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/23/13	07:00:00		-8:00	26.29	N	N/A
	MPOLLARD	<input checked="" type="checkbox"/>	07/23/13	07:00:00	03:00:00 F	8:00	26.29	N	N/A
	GLAM	<input checked="" type="checkbox"/>	07/24/13	06:00:00	02:00:00 F	8:00	26.29	N	N/A
	PMCELFISH	<input checked="" type="checkbox"/>	07/23/13	07:00:00		-8:00	26.29	N	N/A
	TSANTMYER	<input checked="" type="checkbox"/>	07/23/13	07:00:00		-8:00	26.29	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	07/24/13	06:00:00	02:00:00 F	8:00	26.29	N	N/A

Select Labor **Select Planned Labor** **New Row**

TRACK INSPECTION REPORTING FORM

Name G. LAM

Date 7-24-2013

Page 1 of 1

(Please Print)
Watchman BRYANT

Inspected From CAMDEN

To Linthicum

W.O Number 1149311

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	<u>CM 030+20</u>		<u>1149311</u>	<u>1</u>	<u>W</u>	<u>N/A</u>	<u>J301</u>	<u>301 732</u>	<u>Y</u>	<u>N</u>
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

7 TIES Pumping UNDER I.J. IJ Also needs overFlow
metal Grinded out From being battered

Were Switch In the area of Inspected

Yes ☒

NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☒

SPECIAL INSPECTION

Yes ☐

NO ☒

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

[Signature]

Quick Reporting (Tr) Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1149311 TEAM TWO - SECT 4: CY/LINT - CM 16S TC Site: LTRAIL

Classification: MTA \ LTRAIL MTA - LTRAIL Status: COMP

Asset: Priority: 1

Alias: Work Type: PM

Location: CHAIN_MARK LT Rail Chain Markers Crew:

Work Location: Warranty Situation Present? N

Work Group*: MTA527 Maintenance Alert? ☐

Work Details

Component: Total Planned Cost: 0.00

Position: Total Actual Cost: 420.64

Reason for Repair: Repair Limit Amount:

Work Accomplished: Reported By: MTACRON

Part Failure: Reported Date: 07/13/13 12:30:05 AM

Parent WO:

Telematics Code:

Telematics Transaction:

GL Account: J05-####-052

Asset Details

Primary Meter:

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 6 of 8 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/23/13	07:00:00		-8:00	26.29	N	N/A
	MPOLLARD	<input checked="" type="checkbox"/>	07/23/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	GLAM	<input checked="" type="checkbox"/>	07/24/13	06:00:00	02:00:00	8:00	26.29	N	N/A
	PMCELFISH	<input checked="" type="checkbox"/>	07/23/13	07:00:00		-8:00	26.29	N	N/A
	TSANTMYER	<input checked="" type="checkbox"/>	07/23/13	07:00:00		-8:00	26.29	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	07/24/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Labor

Task:

Labor*: MPOLLARD Michael Pollard

Regular Hours*: -8:00

Component:

Position:

Reason for Repair:

Work Accomplished:

Part Failure:

Memo:

Start Date*: 07/23/13 Warranty?: N

Start Time*: 07:00:00 Qualification Met?: N/A

End Date: Approved?: ☒

End Time: Timer Status:

Rate*: 26.29 Craft*: AREPAIR

Line Cost: -210.32 Skill Level:

Type*: WORK

Outside Labor **Premium Pay** **Charge Information**

Outside? ☐ Premium Pay Code: GL Debit Account: J05-####-052

Vendor: Premium Pay Hours: GL Credit Account:

Contract: Premium Pay Rate: Location: CHAIN_MARK

Revision: Premium Rate Type: Asset:

Recorded as Received: Alias:

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name Walter Bryant
(Please Print)

Date 07-25-13

Page 1 of 1

Watchman M. Pollard

W.O Number 1155624

Inspected From Lutherville

To Hunt Valley

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	<u>729+80</u>	<u>-</u>	<u>-</u>	<u>2</u>	<u>W</u>	<u>-</u>	<u>W-301</u>	<u>332</u>	<u>Y</u>	<u>N</u>
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	<u>Track 2. CM 729+80. Industry Lane RD Xing. 6 ties are pumping 1" under load. 3 ties with full ballast. Area is mark in yellow.</u>

Were Switch in the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes ☒ NO ☐

SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special inspection _____

Track Inspector Signature

Supervisory Certification

Walter W. Bryant

[Signature]

Quick Reporting (Tr) Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1155624 TEAM TWO - SECT 1: HV/LU - CM 902N TO Site: LTRAIL
Classification: MTA \ LTRAIL MTA - LTRAIL Status: COMP
Asset: Priority: 1
Alias: Work Type*: PM
Location: CHAIN_MARK LT Rail Chain Markers Crew:
Work Location: Warranty Situation Present?: N
Work Group*: MTA527 Maintenance Alert? ☐

Work Details

Component			Total Planned Cost	0.00
Position			Total Actual Cost	420.64
Reason for Repair			Repair Limit Amount	
Work Accomplished			Reported By	MTACRON
Part Failure			Reported Date	07/19/13 12:38:33 AM
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-####-052			

Asset Details
Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDAR			N			NONE	COMP

labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/25/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	07/25/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name

Pollard

(Please Print)

Date _____

7-25-2013

Page 1 of 1

of

Watchman

Inspected From

Coxhewille

To

do 1d spring

W.O Number

155 631

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

Rechnung

No new defects noted

Track in spectrum complete

Were Switch in the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 NO

Yes _____ NO ✓

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Track Inspector Signature *Michael L. Ball*

Supervisory Certification

Quick Reporting (Tr) Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1155631 TEAM ONE - SECT 2: LU/CS - CM 586N TO Site: LTRAIL
Classification: MTA \ LTRAIL MTA - LTRAIL Status: COMP
Asset: Priority: 1
Alias: Work Type*: PM
Location: CHAIN_MARK LT Rail Chain Markers Crew: DAY
Work Location: Warranty Situation Present?: N
Work Group*: MTA527 Maintenance Alert?: ☐

Work Details

Component			Total Planned Cost	0.00
Position			Total Actual Cost	473.22
Reason for Repair			Repair Limit Amount	
Work Accomplished			Reported By	MTACRON
Part Failure			Reported Date	07/19/13 12:38:57 AM
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-####-052			

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDART			N			NONE	COMP

labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/25/13	03:30:00 F	09:00:00 F	0:00	26.29	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	07/25/13	02:30:00 F	09:00:00 F	0:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name T SCHISLER

Date 7/26/13

Page 1 of 1

Watchman W BRYANT

Inspected From COLL SPRING

To CAMPDEN + ROAD

W.O Number 1155499

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item **COMMENTS**

NO NEW DEFECTS NOTED IN AREA

Were Switch in the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes ☒ NO ☐

SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special Inspection ? _____

Track Inspector Signature

T Schisler

Supervisory Certification

[Signature]

TRACK INSPECTION REPORTING FORM

Name Pollard

Date 7-26-2013

Page / of /

Watchman

(Please Print)

Inspected From

To

W.O Number

Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair	
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.	26540			2	E+W	269-1A	F316	322	Y	N
3.							R304	318	Y	N
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

[illegible]

Were Switch in the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 NO

Yes _____ NO _____

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

Quick Reporting (Tr) Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1155562 TEAM ONE - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL
Classification	MTA \ LTRAIL MTA - LTRAIL	Status	COMP
Asset		Priority	1
Alias		Work Type*	PM
Location	CHAIN_MARK LT Rail Chain Markers	Crew	DAY-A
Work Location		Warranty Situation Present?	N
Work Group*	MTA527	Maintenance Alert?	<input type="checkbox"/>

Work Details

Component	Total Planned Cost
Position	Total Actual Cost
Reason for Repair	Repair Limit Amount
Work Accomplished	Reported By
Part Failure	Reported Date
Parent WO	
Telematics Code	
Telematics Transaction	
GL Account	

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Download

Tasks Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDAR			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/26/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	ARABETTE	<input checked="" type="checkbox"/>	07/26/13	07:00:00	12:30:00	0:00	27.17	N	N/A

Select Labor **Select Planned Labor** **New Row**